

3701 Plano Parkway, Suite 150 / Plano, Texas 75075 P: 972-390-8014 – F: 979-705-7611

Client:	St Michael & All Angels Episcopal Church & School	<u>Job #:</u>	5411.02
Project:	Phase 1-B (Rms 201 thru 218)	Lab Job #:	
Address:	8011 Douglas Avenue Dallas, TX 75225	Rotometer #:	Saul 1 & 2
PPE:	Disp. Suits, ½ face respirator w/ P-100, Safety Glasses, Gloves, & Rubber Boots	Microscope ID:	CX43RF

Sample #	Location	Activity	On Flow Rate LPM	Off Flow Rate LPM	Start Time	Stop Time	Total Minutes	Volume	Fibers/ Fields	Fibers/CC
RS 232.1	QA/QC	QA/QC	N/A	N/A	N/A	N/A	N/A	N/A	103/46	
D87043	FB	FB	N/A	N/A	N/A	N/A	N/A	N/A	0/100	N/A
D87044	FFB	FFB	N/A	N/A	N/A	N/A	N/A	N/A	0/100	N/A
D87045	School Hallway (Reception)	Air Quality Monitor	3.2	3.2	07:09	15:33	504	1612.80	10/100	< 0.005
D87046	School Hallway (Nurse Station)	" "	3.2	3.2	07:02	15:39	517	1654.40	6/100	< 0.005
D87047	School Hallway East End	" "	3.2	3.2	06:54	15:42	528	1689.60	9/100	< 0.005
										·
										·
D87047	Duplicate	Duplicate	3.2	3.2	06:54	15:42	528	1689.60	10.5/100	< 0.005

GENERAL INFORMATION	SAMPLE ACTIVITY		SAMPLE LOCATION			CHAIN OF CUSTODY			
FIELD AREA = 0.00785 sq. mm	BL = Baseline	PR = Prep	AMB = Ambient / Away From Containment		OC = Outside Containment	Collected By:	Saul Nazario	Date: 5/10/24	
LPM=Liters Per Minute	AB = Abatement (Include Material)	GB = Glovebag	AC = At Critical Barrier	CR = Decon Clean Room	HE = HEPA Exhaust	Submitted By:			
FILTER AREA = 385 sq. mm	CL = Cleaning	FC = Final Clearance		EX - Building Exterior		Received By:			
OLM = Overloaded Mixed	BK = Blank	BO = Bag Out	PS = Personal	STEL = Short Term Exposure Limit		Analyzed By:	Saul Nazario	Date: 5/10/24	